

June Work Trip- 2024



Your June 2024 work trip team. Everybody having a bad hair day!



This activity lasted 5 minutes before a pressure washer was purchased.



New pressure washer.



Cyndi painted the inside of the BH outhouse.



Mark-Tami assesses the situation.



Remi and Ryli assess the situation.



Remi says "is there room for me?"



We love Texas! Go longhorns.

June
New dock!



July
New dock with all the accessories!



September Work Trip- Storage building roof replacement and foundation repair.



Rotted fascia boards and OSB roof sheathing.



All fascia boards removed along with rotten sheathing.




New roof sheathing and fascia boards being installed.



Felt paper installed.



Steel roof being installed.



New window installed.



Finished roof and window trim. Gutters in 2025.



Overhead detail using knotty pine tongue and groove.



Siding and frame rot and repair.



New treated lumber front beam.





Floor and siding- finished repair.



1 ton of quartz/granite gravel applied under floor.



Inside view of new window. Arched window was sent to Restore® and other contents removed.



View of new storage building roof from BH steps.



Finished product. Additional windows and gutters will be installed in 2025.



Wood trash pile that needs to be disposed of or burned.



New motion detector porch light installed outside BH kitchen.



Nonny's garden was relocated near Rock Dock!



Waiting on the new dock for Randy's taxi service.



Finished dock was leveled.